

Date: 25 November 2013

ITB/SEC/15/2013 Supply, Delivery and Installation of Beamers and Screens to the OSCE Clarification Note 1

A site visit and pre-bid meeting took place at the OSCE offices in the Hofburg on Thursday 21 November 2013. A number of questions were raised, some of which were answered immediately and some of which required further internal enquiries, as follows:

- 1. Can we use the existing mounts or should our proposal include the cost for new mounts? What is the current model of projector installed?
- The current model is Eiki EIP 4500.
- 2. Cam we use the existing mounts or should our proposal include the cost for new mounts?
- For security reasons please include the cost of new ceiling mounts in your proposal (mandatory).
- 3. Why are the screens required to be silver?
- The noun for a particular type of projection screen in English is 'silver screen'. In fact what is required is a normal projection screen or "Weiße Leinwand".
- 4. What are the dimensions of the room?
- Room size: 33m long x 14m wide x 6.8m high.
- 5. Can we offer alternatives in the bid?
- Yes please offer alternatives models of projector in addition to the ones requested. Please offer a higher specification model of projector with 12,000 lumens as an additional optional component and add explanation why this is required or suggested.
- 6. What existing cabling is installed?
- Current cabling to projectors is CAT6 STP installed in 2006
- 7. Should the quotation include the cost of installation of new cabling or use of existing cabling?
- Both. Please mandatorily quote for installation of equipment on the basis of using existing cabling, and provide a supplemental cost for installation of new cabling if it should prove necessary.

- 8. What guarantee/warranty is required?
- Mandatory guarantee of 2 years (excluding lamps/bulbs or other consumables to be listed)
- 9. What dates are available for installation?
- The winter recess period is from 24th December to 12th January, first session will be on Monday 13th January again. Ideally the work would be completed by then.
- 10. How is the TV screen currently mounted on the wall?
- One of the TV screens is mounted on plaster wall of single "Rigips" (there is a mount currently existing OSCE will take the risk of installation).
- 11. Should we include the cost of maintenance contracts, replacement services and so on in the tender?
- The cost of maintenance contract can be offered separately in the tender as optional components.